ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0273	Pipeline Rd	pipeline 9th cross
Unique Road No.	**Length of full Road(m)**	
13-W0273-9343	21.00	

Road Details

Road From	Road To
pipeline	dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
34.00	3.50			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

☐ Left

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		South

Other Flow Direction Type	Length (m)	Average Width(m)
	34.00	0.60

☐ Right

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		South

Other Flow Direction Type	Length (m)	Average Width(m)
	34.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	yes	BWSSB	yes
OFC		Manholes	2
Others			

Inspection Details

Number of Trees 0

Date of Inspection 16/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0267	NA	pipeline 10th cross
Unique Road No.	**Length of full Road(m)**	
13-W0267-9342	28.00	

Road Details

Road From	Road To
pipeline	dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
54.00	3.80			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

☐ Left

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		South

Other Flow Direction Type	Length (m)	Average Width(m)
	54.00	0.60

☐ Right

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		South

Other Flow Direction Type	Length (m)	Average Width(m)
	54.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		3.50	1.50

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	3
Others			

Inspection Details

Number of Trees 0

Date of Inspection 16/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0232	NA	7th cross
Unique Road No.	**Length of full Road(m)**	
13-W0232-9333	88.00	

Road Details

Road From	Road To
7th cross	6th cross
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
82.00	5.60			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	BS Slab		82.00	1.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	Concrete		82.00	1.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	82.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	82.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		5.00	1.60

Existing Services

BESCOM	yes	BWSSB	yes
OFC		Manholes	2
Others			

Inspection Details

Number of Trees 0

Date of Inspection 16/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0240	NA	kalyananagara 6th crs
Unique Road No.	**Length of full Road(m)**	
13-W0240-10425	68.00	

Road Details

Road From	Road To
6th crs	Stor motor drain
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
71.00	4.80			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	71.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	71.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	yes	BWSSB	yes
OFC		Manholes	3
Others			

Inspection Details

Number of Trees 0

Date of Inspection 16/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		